

AMP6

@ONE ALLIANCE PPE MINIMUM STANDARDS

Management of PPE and Safety Equipment

AMP 6 AW Capital Delivery Minimum PPE Matrix

	PPE item								
Roles	Hard hat*	Hi vis vest /Jacket		Safety boots (ankle protection)		gloves	Glasses (light eye protection)	Hi vis trousers	**Suitable flame retardant overalls/ hi-vis (Arc standard may be required)
		Class 2	Class 3	Standard (lace up, mid sole)	Metatarsal protection				
General site workers	M*	M		M		M	M		M - where **RA identifies need ie hot works/ electrical work
Breaking Ground	M	M			M	M	M		M
Work in highways	M*		M	M		M	M	M	
Visitors	M	M		M		M	M		
Delivery drivers	M	M		M		M	M		
Surveyors (non Construction site)		M	M (if over 40mph)	M*				M (if over 40mph)	

This would only really apply to e.g. Commissioning engineers working in MCC rooms at a desk on a lap top etc.

**Note: normally required however if no risk of head /ankle or foot injury then item could be risk assessed out.*
In addition to PPE specified above, the following PPE may be required for specific tasks (risk assessment based):

Roles	PPE item						
	Goggles / full face protection (medium or high impact)	Respiratory protection – dust masks etc	Hearing protection	Wellington boots	Chin strap for helmet	harness	Life jackets
Work creating airborne particles - Cutting / grinding / drilling masonry and wood	M	M	M				
Work at height					M	M	
Concrete pouring	M			M			
Use of 110v power tools	M		M				
Work near or adjacent water (no protection in place)							M

M = mandatory

Revision 1.0 October 2014

This document was printed on 6-May-15. May be uncontrolled if printed

COLOUR CODED HARD HATS

NB: If you are a slinger and also a supervisor your slinger coloured hat takes priority. A first aid sticker will be fine on the supervisors hat

FIRST AIDER



Left when worn

Right when worn

SLINGER/BANKSMAN



Left when worn

Right when worn

SUPERVISORS



Left when worn

Right when worn

All other site workers, Ops and Staff will wear White hard hats

HI VIS Clothing

NB, If you are first aider or slinger, you do not need to wear a corresponding vest matching the hard hat, a colour coded hat will do.

Coat front



Coat/vest back



Vest front



Visitors may be permitted to wear yellow jackets and vests

Boots for @one Alliance



For normal operations Lace up boots should be worn that provide Ankle protection with steel toe cap and mid sole protection



Boots that provide an extra protection for the Metatarsal will be worn where the RA states that there is Hazard of injuring the top of the foot. For example, using a breaker or Slinger signaller.

FR Overalls for @one Alliance

**FR overalls will be worn
when dictated by a Risk
Assessment for example
if breaking ground or Hot
works etc**



****Note:** When selecting flame retardant overalls appropriate protection must be determined via risk assessment:

EN 11611 – protection against small splashes of molten metal, and brief contact with flame

EN 11612 – protection against brief contact with heat and flame

EN 14116 – protection against occasional and brief contact with small igniting flames

EN 61482-2:2009 – protection against the thermal hazards of an electric arc.